



Early Learning and Childcare Facility Inspection Report

Type of Inspection:
Monitoring Inspection

Pursuant to section 21 of the *Early Childhood Services Act*, operators of licensed early learning and childcare facilities must post their most recent inspection report in a clearly visible and prominent place in the facility.

Name of operator GRAND BAY BAPTIST CHURCH INC	Licence Number 2012758	Inspection Date May 04, 2023	
Facility Name GRAND BAY TREASURED ADVENTURES		Telephone Number (506) 738-2766	
Address 77 Woolastook Drive Grand Bay-Westfield NB E5K 1S3			
Name of Early Learning and Childcare Licensing Staff Cathleen LeBlanc		Position Title Quality Assurance Monitor	
Order for Compliance	Regulation	Date to be corrected	Date corrected
28(3) The premises of a licensed facility shall comply with (a) lighting, ventilation and other general health standards under the Public Health Act.	28(3)(a)	Jun 23, 2023	

Order for Compliance	Regulation	Date to be corrected	Date corrected
<p>Comments:</p> <p>Bathroom 1: Heater is broken. To be fixed. Crack in wall beside toilet. To be fixed. Ceiling Light had no cover. To be covered. Soap dispenser broken. To be replaced. No door stopper. To be added. Hole in wall behind door. To be repaired.</p> <p>Bathroom 2: Cap behind toilet seat missing. To be added.</p> <p>Hallway to Gymnasium: Tile missing and covered with tape. Tile to be replaced. Broken tiles at end of hallway, close to gym. To be replaced.</p> <p>Youth Room: Hole in wall, by entrance. To be fixed. Light switch accumulating debris. To be cleaned. Door missing wood. Door to be repaired and or replaced. Trim around room requires painting. To be repainted. Heater accumulating dust and debris. To be cleaned.</p> <p>Gymnasium: Carpeted walls had several chunks of carpet missing - to be repaired. Heaters accumulating dust and debris. To be cleaned. Broken baseboard right end of gymnasium. To be replaced.</p> <p>Classrooms: Quiet room / book room - Holes in ceiling. To be repaired.</p> <p>Corner area, by steps: Cobweb on floor, by steps. Area to be swept and maintained. Wall by stairs is chipped. Touch ups required.</p> <p>Building Room: Heater broken. To be repaired.</p> <p>Play Kitchen area: Staples in ceiling. To be removed.</p> <p>Art Room: Heater accumulating dust and debris. To be cleaned.</p>			

General Comments
<p>A Monitoring Inspection was completed this afternoon. It was a rainy day and therefore the afterschool children were observed inside. The older group was observed in the gymnasium and youth room. The younger group was observed in the classroom area. Older Group - the older group was observed arriving at the facility. Children were observed washing their hands and entering the gym. The group was split in two, half in the gym and half in the youth room. In the gym, children were observed playing dodgeball, basketball, and hockey. In the youth room, children were observed playing air hockey, bracelet making, playing with the dollhouse, building with Lego, and coloring / drawing. The younger group of children were observed during snack and free play. During free play, children were observed in the following activities: making and flying paper airplanes, building with Lego and gears, play kitchen, reading books, and playing board games. Several learning invitations were observed - airplane making, arts and crafts, Lego displays, etc. Several forms of documentation were observed throughout the facility. Positive child guidance techniques were observed in both groups - educators giving gentle reminders, redirecting negative behaviors, and offering the children the opportunity for new activities. A</p>

General Comments

conversation was had with director regarding the building itself, and the several repairs that are required.

original signed by
Cathleen LeBlanc

Signature of Early Learning and Childcare Licensing Staff

May 04, 2023

Date

original signed by
Alesha Cleghorn

Signature of Operator/Designate

May 04, 2023

Date