



Early Learning and Childcare Facility Inspection Report

Type of Inspection:
Monitoring Inspection

Pursuant to section 21 of the *Early Childhood Services Act*, operators of licensed early learning and childcare facilities must post their most recent inspection report in a clearly visible and prominent place in the facility.

Name of operator 610687 NB Inc.	Licence Number 2006893	Inspection Date July 05, 2023
Facility Name Kingswood Academy 2	Telephone Number (506) 869-8980	
Address 1535 Ryan Street Moncton NB E1G 2V4		
Name of Early Learning and Childcare Licensing Staff Sophie Powers	Position Title Quality Assurance Monitor	

Order for Compliance	Regulation	Date to be corrected	Date corrected
33(2) Stationary equipment in the outdoor play area shall be surrounded by a protective surfacing and installed according to the manufacturer's instructions.	33(2)	May 30, 2023	Jul 05, 2023
Comments: QA monitor was on site to verify if pea gravel was added under the stationary equipment or if it was raked. The stationary equipment must be surrounded by protective surfacing of appropriate depth. Operator informs QA monitor that a new protective surfacing (rubber) will replace the pea gravel next year. In the meantime, the stationary equipment will not be used by children. Operator confirms that the children will be playing in the backyard instead of using the playground equipment. Operator will inform QA monitor when the pea gravel is either added, raked or replaced by rubber. Deficiency is now compliant.			

General Comments
Follow-up monitoring inspection was conducted. QA monitor was unable to verify child-to-staff ratio, because children were gone on an outing to the zoo.

original signed by
Sophie Powers

Signature of Early Learning and Childcare Licensing Staff

July 06, 2023

Date

original signed by
Debra Betsch

Signature of Operator/Designate

July 06, 2023

Date