

## Early Learning and Childcare Facility Inspection Report

Type of Inspection:  
Follow-Up Inspection

Pursuant to section 21 of the *Early Childhood Services Act*, operators of licensed early learning and childcare facilities must post their most recent inspection report in a clearly visible and prominent place in the facility.

Name of operator YMCA OF GREATER SAINT JOHN INC.	Licence Number 2016892	Inspection Date August 16, 2019
Facility Name YMCA Early Learning Centre Preschool and After School		Telephone Number (506) 646-2106
Address 223 St. James Street Saint John NB E2L 1W3		
Name of Early Learning and Childcare Licensing Staff Jodi Hennessey		Position Title Inspector

Order for Compliance	Regulation	Date to be corrected	Date corrected
24(1) For the purposes of subsection 20(1) of the Act, the following records and documents shall be maintained on the premises of a licensed facility: (b) child records that include: (i) the child's name, address, birth date and Medicare number, Comments: Deficiency is now compliant	24(1)(b)(i)	Aug 16, 2019	Aug 16, 2019
28(3) The premises of a licensed facility shall comply with (a) lighting, ventilation and other general health standards under the Public Health Act. Comments: Deficiency is now compliant	28(3)(a)	Aug 16, 2019	Aug 16, 2019
30(3) An operator shall maintain the indoor play area of a licensed facility to ensure the safety of the children. Comments: Deficiency is now compliant	30(3)	Aug 16, 2019	Aug 16, 2019
31(3) An operator shall maintain the outdoor play area of a licensed facility to ensure the safety of the children. Comments: Deficiency is now compliant	31(3)	Aug 16, 2019	Aug 16, 2019
33(2) Stationary equipment in the outdoor play area shall be surrounded by a protective surfacing and installed according to the manufacturer's instructions. Comments: Deficiency is now compliant	33(2)	Aug 16, 2019	Aug 16, 2019

<b>General Comments</b>
<p>Follow up to renewal inspection:</p> <p>Educators have created engaging environments and were observed interacting with the children in the learning and conversations.</p> <p>Discussed the outside play area/large climbing structure. This is not to be used by the children attending the ELC as it does not meet CSA standards for surfacing and cribbage work around structure requires repairs. The school-age children utilize the grass area adjacent to the climbing structure.</p>

original signed by  
Jodi Hennessey

\_\_\_\_\_  
Signature of Early Learning and Childcare Licensing Staff

August 16, 2019

\_\_\_\_\_  
Date

original signed by  
Avril Wood-Toner

\_\_\_\_\_  
Signature of Operator/Designate

August 16, 2019

\_\_\_\_\_  
Date